

Globe Theatre Reconstruction, 1999.

European Oak timber, Douglas Fir plywood.



DRICON®

NON-COM®
EXTERIOR

Interesting Fact:

- Investigation was needed to ensure the compatibility between timber and treatment.

