

# Thurland Castle, Tunstall, 1997.

Oak panelled hall and staircase.

**FLAMECHECK**



Interesting Facts:

- **Due to the nature of the application, it was not necessary to remove the panelling for treatment.**
- **Treated staircase links the wedding chamber and reception areas.**